

**PETROLEUM BULK STORAGE/GASOLINE DISPENSING SITES  
REGISTRATION CERTIFICATE**

<b>Site:</b> Station #55839 747 Main Street New Rochelle, NY 10805	<b>PBS ID:</b> 3-174017	<b>Issue Date:</b> 04/07/2016 <b>Expiration Date:</b> 10/16/2018				
<b>Operator:</b> Adnan Kiriscioglu - (551) 556-4133	<b>Owner:</b> 999 Route 25A Stony Brook, LLC 2664 Route 112 Medford, NY 11753					
<b>Emergency Contact:</b> Main Office (201) 866-9000	<b>Issued by:</b> Sherita Amler, M.D. Commissioner of Health					
As an authorized representative of the above-named facility, I affirm under penalty of perjury that the information displayed on this form is correct to the best of my knowledge. I recognize that I am responsible for assuring that this facility is in compliance with all sections of Article XXV and XXVI of the Westchester County Sanitary Code. <ul style="list-style-type: none"><li>• The facility must be re-registered upon a transfer of ownership.</li><li>• The Department must be notified within 15 days prior to adding, replacing, reconditioning or permanently closing a stationary tank.</li><li>• THIS CERTIFICATE MUST BE POSTED ON THE PREMISES AT ALL TIMES. Posting must be at the tank, at the entrance of the facility or at the main office where the storage tanks are located.</li><li>• Any person with knowledge of a spill, leak or discharge must report the incident immediately to the Westchester County Department of Health at 914-813-5000 and to the New York State Department of Environmental Conservation at 800-457-7362.</li></ul>						
<b>Tank ID</b>	<b>Date Installed</b>	<b>Tank Location</b>	<b>Product</b>	<b>Capacity (gallons)</b>	<b>Last Tested</b>	<b>Next Test Due</b>
20	03/2004	Aboveground on saddles, legs, stilts, racks or cradle	#2 Fuel Oil	280		*
Vapor Recovery ID: 3551000381						
<b>Mailing Address:</b> 999 Route 25A Stony Brook, LLC 8012 Tonnelle Avenue North Bergen NJ 07047			<b>Name of Authorized Representative/Owner (print)</b>  <b>Signature of Authorized Representative/Owner</b>  <b>Title</b>  <b>Date</b>			

THIS CERTIFICATE IS NON-TRANSFERABLE



Facility: Station #58839 747 Main Street New Rochelle, NY 10805  Operator: Adnan Kirsicloglu Operator phone: (551) 556-4133 Emergency: Main Office Emergency phone: (201) 866-9000  Owner: 999 Route 25A Stony Brook, LLC 2664 Route 112 Medford, NY 11753  Type of ownership: Corporation Phone: (551) 556-4133	PBS no.: 3-174017 Reg. issued: 04/07/2016 Reg. expires: 10/16/2018 Last inspected: 06/23/2020 Vapor recovery ID: 3551000381 Last Stage II test: Next Stage II test due: Site Type: Retail Gasoline Sales  Mail: 999 Route 25A Stony Brook, LLC 8012 Tonnelle Avenue North Bergen, NJ 07047  Phone: (201) 866-9000 Email:
--	--

TankID	20	19	10
Tank Location	3. Aboveground on saddles, legs, stilts, racks or cradle	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection
Status	1. In-Service	3. Closed - Removed	3a. Closed - Prior to 04/1991
Install	03/01/2004	08/01/1983	09/01/1962
Capacity	280	550	2000
Product	0001. #2 Fuel Oil		
%			
Tank Type	1. Steel/Carbon steel/iron	1. Steel/Carbon steel/iron	1. Steel/Carbon steel/iron
Tank Internal Protection	0. None	0. None	0. None
Tank External Protection	1. Painted/Asphalt Coating	0. None	0. None
Tank Secondary Containment	0. None	0. None	0. None
Tank Leak Detection	0. None	99. Other	4. Groundwater Well
Tank Overfill Prevention	3. Automatic Shut-off	5. Vent Whistle	
Pumping/Dispensing Method			
Spill Prevention	1. Catch Basin		
Piping Location	1. Aboveground	2. Underground/on ground	
Piping Type	10. Copper	10. Copper	1. Steel/Carbon/ steel/iron
Piping External Protection	0. None	0. None	0. None
Piping Secondary Containment	0. None		
Piping Leak Detection	0. None		
Last Test			
Next Test Due	*	*	*
Closed		03/01/2004	

TankID	11	12	13
Tank Location	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection
Status	3. Closed - Removed	3. Closed - Removed	3. Closed - Removed
Install	08/01/1983	08/01/1983	04/01/1988
Capacity	4000	4000	4000
Product	0008. Diesel	0008. Diesel	2712. Gasoline/Ethanol
%			
Tank Type	6. Fiberglass reinforced plastic (FRP)	6. Fiberglass reinforced plastic (FRP)	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection	0. None	0. None	0. None
Tank External Protection	4. Fiberglass	4. Fiberglass	4. Fiberglass
Tank Secondary Containment	0. None	0. None	4. Double-Walled (underground only)
Tank Leak Detection	5. In-Tank System (auto tank gauge)	5. In-Tank System (auto tank gauge)	1. Electronic Interstitial Monitoring
Tank Overfill Prevention	2. High Level Alarm	1. Float Vent Valve	1. Float Vent Valve
Pumping/Dispensing Method	1. Pressurized Dispenser	1. Pressurized Dispenser	1. Float Vent Valve
Spill Prevention	1. Catch Basin	1. Catch Basin	1. Catch Basin
Piping Location	2. Underground/on Ground	2. Underground/on Ground	2. Underground/on Ground
Piping Type	6. Fiberglass Reinforced Plastic (FRP)	6. Fiberglass Reinforced Plastic (FRP)	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection	4. Fiberglass	4. Fiberglass	4. Fiberglass
Piping Secondary Containment	4. Double-Walled (underground only)	4. Double-Walled (underground only)	4. Double-Walled (underground only)
Piping Leak Detection	2. Manual Interstitial Monitoring	2. Manual Interstitial Monitoring	2. Manual Interstitial Monitoring
Last Test	04/08/2016	04/08/2016	09/15/2015
Next Test Due	*	*	*
Closed			

TankID	14	15	16
Tank Location	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection
Status	3. Closed - Removed	3. Closed - Removed	3. Closed - Removed
Install	04/01/1988	04/01/1988	04/01/1988
Capacity	4000	4000	4000
Product	2712. Gasoline/Ethanol	2712. Gasoline/Ethanol	2712. Gasoline/Ethanol
%			
Tank Type	6. Fiberglass reinforced plastic (FRP)	6. Fiberglass reinforced plastic (FRP)	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection	0. None	0. None	0. None
Tank External Protection	4. Fiberglass	4. Fiberglass	4. Fiberglass
Tank Secondary Containment	4. Double-Walled (underground only)	4. Double-Walled (underground only)	4. Double-Walled (underground only)
Tank Leak Detection	1. Electronic Interstitial Monitoring	1. Electronic Interstitial Monitoring	1. Electronic Interstitial Monitoring
Tank Overfill Prevention	1. Float Vent Valve	1. Float Vent Valve	1. Float Vent Valve
Pumping/Dispensing Method			
Spill Prevention	1. Catch Basin	1. Catch Basin	1. Catch Basin
Piping Location	2. Underground/on Ground	2. Underground/on Ground	2. Underground/on Ground
Piping Type	6. Fiberglass Reinforced Plastic (FRP)	6. Fiberglass Reinforced Plastic (FRP)	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection	4. Fiberglass	4. Fiberglass	4. Fiberglass
Piping Secondary Containment	4. Double-Walled (underground only)	4. Double-Walled (underground only)	4. Double-Walled (underground only)
Piping Leak Detection	2. Manual Interstitial Monitoring	2. Manual Interstitial Monitoring	2. Manual Interstitial Monitoring
Last Test	09/19/2015	09/15/2015	09/15/2015
Next Test Due	*	*	*
Closed			

TankID	17	18	
Tank Location	5. Underground including vaulted with no access for inspection	5. Underground including vaulted with no access for inspection	
Status	3. Closed - Removed	3. Closed - Removed	
Install	04/01/1988	04/01/1988	
Capacity	4000	4000	
Product	2712. Gasoline/Ethanol	2712. Gasoline/Ethanol	
%			
Tank Type	6. Fiberglass reinforced plastic (FRP)	6. Fiberglass reinforced plastic (FRP)	
Tank Internal Protection	0. None	0. None	
Tank External Protection	4. Fiberglass	4. Fiberglass	
Tank Secondary Containment	4. Double-Walled (underground only)	4. Double-Walled (underground only)	
Tank Leak Detection	1. Electronic Interstitial Monitoring	1. Electronic Interstitial Monitoring	
Tank Overfill Prevention	1. Float Vent Valve	1. Float Vent Valve	
Pumping/Dispensing Method			
Spill Prevention	1. Catch Basin	1. Catch Basin	
Piping Location	2. Underground/on Ground	2. Underground/on Ground	
Piping Type	6. Fiberglass Reinforced Plastic (FRP)	6. Fiberglass Reinforced Plastic (FRP)	
Piping External Protection	4. Fiberglass	4. Fiberglass	
Piping Secondary Containment	4. Double-Walled (underground only)	4. Double-Walled (underground only)	
Piping Leak Detection	2. Manual Interstitial Monitoring	2. Manual Interstitial Monitoring	
Last Test	09/15/2015	09/15/2015	
Next Test Due	*	*	
Closed			

TankID			
Tank Location			
Status			
Install			
Capacity			
Product			
%			
Tank Type			
Tank Internal Protection			
Tank External Protection			
Tank Secondary Containment			
Tank Leak Detection			
Tank Overfill Prevention			
Pumping/Dispensing Method			
Spill Prevention			
Piping Location			
Piping Type			
Piping External Protection			
Piping Secondary Containment			
Piping Leak Detection			
Last Test			
Next Test Due			
Closed			

TankID	
Tank Location	
Status	
Install	
Capacity	
Product	
%	
Tank Type	
Tank Internal Protection	
Tank External Protection	
Tank Secondary Containment	
Tank Leak Detection	
Tank Overfill Prevention	
Pumping/Dispensing Method	
Spill Prevention	
Piping Location	
Piping Type	
Piping External Protection	
Piping Secondary Containment	
Piping Leak Detection	
Last Test	
Next Test Due	
Closed	